

Holmes County Fair Rules 2011

10,500 and 12,000 lb. Open Farm Stock Rules:

1. No pressurized fuel , diesel fuel only!
2. Maximum drawbar height 20". 18" from center of rear axle.
3. Wheelie bars are required.
4. Side shields are recommended.
5. Fly wheel blanket or steel shield around flywheel is required.
6. Working fire extinguisher recommended.
7. Roll bar or roll cage recommended.
8. All tractors must have an air shut off to be hooked to the sled.
9. Dead man throttle recommended.
10. Injector pump (P pump max.)
11. 20.8.38 uncut tires. No cut tires allowed.
12. All tractors must have stock intake and exhaust manifolds.
13. All tractors must have a hitching device of no more than 1.5" thick and 3.75" in diameter hole. (Absolutely no clevis will be allowed.)
14. Factory weight brackets and factory weights are to be used in factory location. Rear weights cannot interfere with hooking and unhooking sled.
15. All tractors will be equipped with a RPM sensor on the front of the engine on the damper pulley. All wiring ran to the rear of the tractor in visible site to a three prong 110 female plug, use flat spades of the plug 14-16 gauge wire with splices. Mount this plug next to the air shut off cable on rear of the tractor.
(3000 RPM limit MAX. or you are DISQUALIFIED. NO QUESTIONS!)
16. All tractors must have a wide front end in the factory location.
17. The JUDGES and pull committees decisions are FINAL.

Holmes County Fair Rules 2011

Antique tractor pull rules

1. Classes A and B - 1962 and older tractors , speed limit 5 mph ,
cut tires are allowed no turbos allowed.
2. Class C - Columbiana County Antique rules apply 6000 rpm limit
3. Class D - 1962 and older tractors , speed limit 6 mph ,
cut tires are allowed no turbos allowed.

(Only 1 tractor entry per class.)